

PRODUCT LINE CARD

HIGH PRESSURE COOLANT / FILTRATION



UltraFlex



Coolant Chiller



Mist Collector





EcoClean



CoolVac



TL Series



MasterAll Fluids

AUTOMATION

WORKHOLDING



Bar Feeders



Robotic Systems



Tombstones, Trunnions, Indexers



Rotary Tables





Big Mouth Air Chucks



Collet Chucks



Ultimate Chuck







Steady Rests

Cylinders

5th Axis



PRODUCT LINE CARD

*

COOLANT AND FILTRATION PROCESS SOLUTIONS		AU	AUTOMATION SOLUTIONS	
ATS SOLUTION	SOLVING FOR	ATS SOLUTION	APPLICATION	
CoolJet High Pressure	 Stringers or blue chips Poor chip evacuations/re- cutting chips Poor part finish Poor tool life and tool failure Slow speeds and feeds 	KME Tombstones	 Horizontal machines where applications have several operations requiring numerous setup changes 	
CoolJet Chiller	 Coolant temperature fluctuations Heat related tolerance issues 	KME Trunnions	 Vertical machines looking for a higher level of automation and increased productivity 	
MistBuster	 Poor shop air quality (mist and smoke) Suitable for water and oil coolants 	KME Indexers	 Vertical machines looking for a higher level of automation and increased productivity 	
MasterAll Coolants	 Coolant issues such as foaming or poor tool life 	Rotary Tables	 Vertical machines looking for a higher level of automation and increased productivity 	
CoolVac	 Excessive buildup of chips in the machine tank 	ATS Systems Barfeeders	 High level of automation running bar stock 	
EcoClean	 Bad-smelling coolant Cast metal or grinding application issues 	Robotic Systems	 High mix, low volume parts runs looking for a high level of automation 	
Oil Skimmer	 ✓ Poor tool life ✓ Coolant contaminated way 	WORKHOLDING SOLUTIONS		
	lube oil	ATS SOLUTION	APPLICATION	
CoolMag	 Dirty coolant (oil) Filtration issues in ferrous metal applications 	UC3 Ultimate Chuck	 High mix of parts needing to change chuck jaws and parts quickly 	
FOR MORE INFORMATION		ATS Systems Big Mouth Air Chucks	 Running large diameter bars or pipes 	
	800-321-1833 sales@atssystems.us	ATS Systems Collet Chucks	 Running bar stock and needing a better and more accurate workholding solution than a 3-jaw chuck 	
	www.atssystems.us	Steady Rests	 Running long bars or shafts requiring added support 	
		5th Axis	 Horizontal and vertical machining operations where zero-point quick change fixturing can be used to increase productivity 	